

Elcometer 308 & 309 Digital Hygrometers

The **Elcometer 308 Hygrometer** has been specifically designed for use in very hot climates where the surface temperature of the substrate can exceed the paint manufacturer's recommended limits for successful painting.

Painting outside recommended limits can have a detrimental affect on the performance and lifetime of the coating. The Elcometer 308 Hygrometer provides a simple and fast measurement of relative humidity and surface temperature.

The **Elcometer 309 Delta T Hygrometer** provides a simple and fast measurement of the two critical climate parameters within coatings:

- **Delta T (T Δ):** The difference between the surface temperature (Ts) and the dewpoint temperature (Td). When T Δ is less than 3°C (5°F) painting should not occur.
- **Relative Humidity (RH):** Expressed as a percentage, RH is the ratio of the amount of water vapour actually held by the air compared to the maximum amount of water vapour the air could hold at a given temperature. Typical maximum RH values specified by paint manufacturers are between 75% and 85%.



Elcometer 308



Elcometer 309

STANDARDS:

BS 7079-B4 (Elcometer 309),
ISO 8502-4 (Elcometer 309)

Technical Specification

Model	Elcometer 308 Hygrometer	Elcometer 309 Delta T Hygrometer	Certificate
Part Number	G308----1	G309----1	●
	T _s RH	T Δ RH	
Operating Range	-20°C to +80°C (-4 °F to +176°F)	-20°C to +80°C (-4 °F to +176°F)	
Surface Temperature (TS)	-20°C to +80°C (-4 °F to +176°F)	-20°C to +80°C (-4 °F to +176°F)	
Relative Humidity (RH) & Accuracy*	0% to 100% RH (\pm 3%)	0% to 100% RH (\pm 3%) (Default upper limit 75%, user adjustable)	
Resolution	0.1°C (0.1°F) / 0.1%	0.1°C (0.1°F) / 0.1%	
Power Supply	2 x AA batteries or via USB Cable	2 x AA batteries or via USB Cable	
Battery Life	Greater than 40 hours (Backlight off)	Greater than 40 hours (Backlight off)	
Dimensions & Weight	180 x 75 x 35mm (7 x 3 x 1.4") 300g (10.6oz)	180 x 75 x 35mm (7 x 3 x 1.4") 300g (10.6oz)	
Packing List	Elcometer 308 Hygrometer, wrist strap, 2 x AA batteries, protective carry case/pouch with belt clip, RH & surface probe calibration certificate and operating instructions.	Elcometer 309 Delta T Hygrometer, wrist strap, 2 x AA batteries, protective carry case/pouch with belt clip, RH probe calibration certificate and operating instructions.	

● Basic Calibration Certificate supplied as standard.