



CEM

DT-3386 CLAMP METER

Professional Heavy
Duty 1000 Amp / Volt
AC/DC Clamp Meter

50,000 Count

An easy to see large
backlit display

True RMS
measurement for AC
Volts & AC Amps

NCV detection plus
built-in flashlight

Double moulded
plastic housing

Flexible current probe
expands the
measurement range
to 3000 A AC

Functions

AC/DC Current measurement; AC True RMS; 50000 counts LCD display; Backlight; Built in flashlight; 3000A ACA flexible clamp; Data Hold & Peak Hold; Max /Min; REL (Zero) function; Auto power off; Low battery indication; 48mm Jaw opening; NCV Detection

Specifications

Function	Max Range	Basic Accuracy
Voltage DC	1000V	$\pm(0.1\%+4d)$
Voltage AC	1000V	$\pm(1.0\%+3d)$
Current DC	1000.0A	$\pm(2.5\%+5d)$
Current AC	1000.0A	$\pm(2.5\%+5d)$
Resistance	50M Ω	$\pm(3.0\%+5d)$
Temperature	1000 $^{\circ}$ C	$\pm(1.0\%+2.5^{\circ}$ C)
Capacitance	5mF	$\pm(3.5\%+10d)$
Frequency	10MHz	$\pm(0.3\%+2d)$
ACA flexible clamp	3000A	$\pm(2.8\%+8d)$
Continuity check	Buzzer sounds at 50 Ω	
Diode test	Test current 0.3mA	